



Note: The small, blue tool is a temperature adjustment tool for electronic "process control" engineers/supervisors to set and lock the iron temperature so operators cannot accidentally or intentionally change the temperature of the iron. This is particularly useful when soldering delicate or temperature sensitive electronic components.

This tool is not needed by stained glass artisans.